



SO.IS.494.3

SO.IS.494.3  
Rekonštrukcia SLP HDPE  
OK Benestra - vzdušné vedenie

Kablo

Mlynské nivy

Karadžičova

Karadžičova

# 21846/4

# 21846/5

9778

9775/1

9775/10

9775/11

9776

9775/2

# 21845

9094

9093/1

9081/3

21760/4

9079/1

# 21863/2

# 21290/4

d  
9095/14

9095/13

d  
9095/7

d  
9095/15

9095/16

9095/3

# 21293/15

# 21293/17

# 21293/18

# 21293/16

9781/4

9872

9871/102

9871/121

9871/103

9871/129

9881/4

21847/3

9871/115

9871/113

9871/114

9871/112

21290/27

21290/26

21290/28

21290/20

9871/119

21290/19

9871/116

21290/24

21290/23

21290/5

21290/30

21290/22

9871/107

9871/108

9871/100

9871/117

9871/109

21844/2

21844/1

9871/92

9773

21798/4